

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 136 Const Calendar Day: 372 Date: 15-Sep-2010 Wednesday Inspector Name: Bruce, Matt Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 07:00 am 05:30 pm **Break:** 00:30 **Over Time:** 02:00

Federal ID: Location:

Reviewer: Mathur, Lalit Approved Date: 24-Jan-11 Status: Approved

04-SF-80-13.2/13.9 Self-Anchored Suspension Bridge

04-0120F4

Run date 19-Nov-14

Time

5:32 PM

Weather

Temperature 7 AM 60 - 70 **12 PM** 60 - 70 **4PM** 60 - 70

Precipitation 0.00" Condition Overcast in the AM to sunny in the PM

Working Day 🗸 If no, explain:

Diary:

Work description.

- Surveyed punchmarks placed by ABF surveyors on the W2W2 west deviation saddle. In general the points were placed on the outer edge of the top saddle ribs, at the corners of the trough, and on the corner of the top portion of the base plate at 50mm offset from the edges.
- Intermittently observed the verification of the Boltight jacks done in the Pier 7 warehouse by ABF under the supervision of METS inspector Erin McCrory and Alex Schmidt. The Boltight jacks will be used for various stressing operations on the project however the type being verified will be the used for the deviation saddle anchor rods. See Alex's diary for more details as he was primarily responsible for this operation.
- Conco carpenters began to construct the soffit/working platform for the upper bikepath pedastol on the southwest end of the W2 cap beam.
- See Lalit's diary for ABF and Concos labor, equipment and other operations at the W2 cap beam.

04-0120F4	Bid Item:	048	0-W2C-CLO.048	W2 Cap Closure Bar reinforcing steel (bridge)						
REGIONAL STE	EL CORP.									
Labor										
Trade	Clas	ss Nan	ne	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute					
Contractor:	REGIONAL ST	TEEL CORP.								
Ironworker	FOR	R DA\	/ID GARCIA	2.00 0.00 0.00 2.00						
Diary:					Dispute					
Work desc	ription.		048 0-W	/2C-CLO.048						
- Were onsite to assess the female couplers for the two lower bikepath peadastol blockouts located on the south end of the W2 cap beam. No work was performed however the expectations on the quality of the work were given to the ironworker onsite. These include but are not limited to cleaning the threads from rust/debris, T-heads to be aligned all in one plane, use a certified torque wrench and operator, etc.										
04-0120F4	Bid Item:	: 063	W-W2C-HIK.063	W Line W2 Cap Hinge K						
In Place Machini	ng Company									
Labor										
Trade	Clas	ss Nan	ne	RT Hrs OT Hrs Total Remarks	Dispute					
Contractor:	In Place Mach	ining Company	/							
None of the	Above JNM	I CO	HL WEISBROOKE	8.00 4.00 0.00 12.00						
Diary:					Dispute					



Page 1 of 2

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Bruce, Matt Diary #: 136 Date: 15-Sep-2010 Wednesday

Work description.

063 W-W2C-HIK.063

CCO#153

- The cutting apparatus had a serial number of 5759 and a model number of AX48120.
- Continued to rough cut the 7 degree bevel on the end of the second Hinge K pipe beam. This cut was started at 5pm yesterday after the cutting apparatus was mounted on the end of the pipe.
- The schedule for the machinist to complete the work for CCO#153 are 12 hour days for 7 days a week. This CCO work is anticipated to last approximately one month.
- See Bob Brignano's diary for additional details regarding the beveling/quality for this operation.

04-0120F4	Bi	d Item:	063	W-V	V2C-HI	K.063	W Line W	2 Cap H	inge K			
AMERICAN BRID	OGE/F	LUOR,	A JV									
Equipment											Rental Company	
Equipment	ID	Descrip	tion				RT Hrs	OT Hrs	ST Hrs	IT Hrs	Remarks	Dispute
Contractor:	AMER	RICAN BR	IDGE/FLU	OR, A J\	/							
002082		WELDI	NG MACH	INE, MILL	ER 250	AMP					No	
							8.00	4.00	0.00	0.00)	
002076		AIR CO	MPRESSO	DR-DSL/F	PORTAE	BLE, 185 CF	M				No	
							8.00	4.00	0.00	0.00)	
Diary:												Dispute
Work description. 063 W-W2C-HIK.063												
 Supported operation. 	In P	lace M	achinin	ig to m	obiliz	e equipr	ment and	provid	led any	other	support to facilitate their	

Attachment



ABF changed out a boom section of the Manitowoc Ringer crane prior to erecting the first segment of the W2W west deviation saddle.



Punchmarks were placed and surveyed on strategic locations of the W2W2 west deviation saddle prior to erection.

